# Fusion Headquarters, Inc.

15500 NE Kincaid Road - Newberg, OR 97132 (503) 538-5281 Fax: (503) 538-6527 Issued By: Carmen Reynolds

### **Product Name:**

**Fuse Master Super Spray** 

Page 1 of 3

FUSION HEADQUARTERS, INC. 15500NE Kincaid Rd. Newberg OR 97132 (503) 538-5281

Section I: General Information:

Supplier: Fusion Headquarters, Inc.

15500 NE Kincaid Road Newberg, OR 97132

Phone: (503) 538-5281 Date Prepared: 10-18-03

Emergency Number: Poison Control 1-800-222-1222

Section II: Hazardous Ingredients:

Dangerous Components: CAS# Weight% PEL TLV Frit 20-22 (65997-18-4).029 MG B/CU PEL Ethyl Alcohol (64-17-5)20-22 .029 MG B/CU PEL Isopropyl Alcohol (67-63-0).25-02.5 .002 MG B/CU PEL Methyl Isobutyl Ketone (108-10-1)Less than 1 trace MG B/CU PEL

Section III: Physical Data:

Boiling Point: Specific Gravity (H2O =1):

212+ F Approximately 1.5

Vapor Pressure (mm Hg.): Percent Volatile By Volume (%):

33 @20C 20%

Vapor Density (air=1): Evaporation Rate (BuAc = 1):

Heavier than air Similar to H2O

### Section IV: Fire and Explosion Hazard Data:

Flash Point: Non-Flammable

Extinguishing Media: Material will not burn, however use water to cool metal containers down

Fire Fighting Procedures, Special: None Required

Percent Volatile: 0%

Solubility in Water: Infinite in water

Appearance and Odor: Liquid, slight alcohol odor

PH – Value – Slightly Alkaline

Unusual Fire Explosion Hazards: Toxic Fumes may be evolved during a fire.

Melting Point: 1300 F

## **Product Name: Fuse Master Super Spray**

FUSION HEADQUARTERS, INC. 15500NE Kincaid Rd. Newberg OR 97132 (503) 538-5281 Page 2 of 3

### Section V: Health Hazard Data:

General Information and First Aid Procedures: No special measures required.

Inhalation: Supply fresh air, consult a physician.

Skin Contact: Wash with mild soap and warm water, consult a physician.

Eye Contact: Rinse open eye with water for at least 15 minutes, consult a physician.

Ingestion: If conscious, give large quantities of water or milk. Induce vomiting, call a physician.

### Section VI: Reactivity Data:

Stability: Stable

Hazardous Polymerization: Will not occur

## Section VII: Spill or Leak Procedures:

Spill Procedures: Use appropriate protective equipment during clean up. Notify the National Response Center if reportable quantities are exceeded. Vacuum with a H.E.P.A. filter or use wet clean-up techniques and place recovered materials in a closable container.

Waste Disposal Methods: Dispose in accordance with federal, state and local regulations.

Emergency Number: CHEMTREC 800-242-9300

## Section VIII: Special Protection Information:

Ventilation: Use adequate, localized ventilation for all handling.

Protective Gloves: Rubber gloves recommended.

Eye Protection: Use safety goggles or glasses to protect from dust particles.

Respiratory Protection: Use of NIOSH approved respirator equipped with dust, fume and mist

H.E.P.A. filter cartridge during all handling operations recommended.

## Section IX: Special Precautions:

Handling, shipping and Storing Precautions:

Avoid breathing dust. Use with adequate localized ventilation. Avoid contact with skin, eyes and clothing. Wash thoroughly after handling. Keep away from food and food products. For manufacturing use only. Keep in sealed closed containers.

### Section X: Right to Know Information:

Chemical Name: Frit (CAS# 65997-18-4)

### **Product Name:**

## **Fuse Master Super Spray**

FUSION HEADQUARTERS, INC. 15500NE Kincaid Rd. Newberg OR 97132 (503) 538-5281 Page 3 of 3

California Proposition 65: (1) Lead and lead compounds are known to the State of California to cause birth defects or reproductive harm. (2) Cobalt oxide is known to the State of California to cause cancer. (3) Silica, crystalline (particles of respirable size) are known to the State of California to cause cancer.

### Section XI: References:

Department issuing data specification sheet: Environmental Protection Department Pfann B.V., Hilversum, Holland

Disclaimer: Employers should use this information only as a supplement to other information gathered by them, and should make independent judgements of suitability of this information to ensure proper use and protect the health and safety of employees. This information and recommendations contained herein are based upon data believed to be correct. However, no guarantee or warranty of any kind expressed or implied is made with respect to the information contained herein.